



Acquire Fire Protection, Inc.
 17012 Kinsman Rd, Middlefield OH 4406
 Tel: 440-632-5600 rkaser@acquirefireprotection.com

Annual

Conferred with: **Clark Baker**
 Report to: **DeMilta Iron & Scrap**
 Street: **3900 Ben Hur Ave.**
 City & State: **Willoughby, Ohio 44094**

Fire Loss Control, Inc., #53 52 1003
 Inspector: Dan Sammon, #54 52 1624
 Inspector: Joe Sammon, #54 18 1823
 Date of Inspection: **February 23, 2016**

FIRE DETECTION SYSTEM FUNCTIONAL TESTING

ITEM		YES	NO	COMMENT
1.	Was a complete set of fire alarm documentation available for use during the inspection?		✓	
2.	Are all smoke and heat detectors in place?	N/A		
3.	Are all fire alarm appliances still suitably positioned (i.e. they have not been compromised by any building modifications)?	✓		
4.	Has functional testing been completed on all fire alarm appliances today?		✓	Horn strobe – System Sensor 12Vdc
5.	Were all fire alarm detection appliances free of exposure to fire since the last inspection?	✓		
6.	Did all visual and functional testing of the fire alarm panel and its associated power sources show it to be in good working order?		✓	FAP Type: Vista 32FB Batteries (size, readings and date): [1] 12Vdc 7Ah [undated] Reading: 13.23Vdc 8.30Ah Circuit Breaker: Location: N/A
7.	Did all audible and visual appliances perform properly?		✓	
8.	Did the Central Station receive signals from Fire Alarm Panel events?	N/A		
9.	Were the system and its appliances restored to their normal operational mode and the management notified that the testing was complete?	✓		DSC Cellular Dialer

Recommendations

1. Sounder is broken on keypad, does not sound trouble. Recommend repair or replacement.
2. Waterflow switch is wired incorrectly and will not activate horn strobe. Facility to contact installers and have them correct the wiring. Retest.

PSD	Photoelectric Smoke Detector
ISD	Ionization Smoke Detector
D	Damper
DD	Duct Detector
DHSD	Door Holder Smoke Detector
SSSD	Single Station Smoke Detector
BD	Beam Detector
PS	Pull Station
RRHD	Rate of Rise Heat Detector
HD	Fixed Temp Heat Detector
FD	Flame Detector
FP	Fire Phone
B	Bell
H	Horn
Spk	Speaker
HS	Horn Strobe
S	Strobe
TS	Tamper Switch
W	Waterflow
DH	Door Holder
NC	Nurse Call
ANN	Annunciator
ML	Magnetic Lock
SS	Speaker Strobe

Copy To: **Willoughby Fire Prevention**
 mkocab@willoughbyohio.com

Submit copy
 to insurance agent
 for rate credit

Fire Loss Control, Inc.
590 Pearl Rd. Brunswick OH 44212
Tel: 330-460-6930 Fax: 330-680-5399 info@firelosscontrol.com

Fire Alarm Panel Monitored Appliances

Item #	Device	Floor No.	Location	Zone	Pass	Fail	Comment
1.	W	1	Sprinkler Riser			✓	Incorrectly wired
2.	TS	1	Backflow 1	004			See sprinkler report
3.	TS	1	Backflow 2	005			See sprinkler report
4.	HS	1	Outdoor Riser Room			✓	Unable to test

Comments



Acquire Fire Protection, Inc.
 17012 Kinsman Rd, Middlefield OH 4406
 Tel: 440-632-5600 rkaser@acquirefireprotection.com

Annual

Conferred with: **Clark Baker**
 Report to: **DeMilta Iron & Scrap**
 Street: **3900 Ben Hur Ave.**
 City & State: **Willoughby, Ohio 44094**

Fire Loss Control, Inc., #53 52 1003
 Inspector: Dan Sammon, #54 52 1624
 Inspector: Joe Sammon, #54 18 1823
 Date of Inspection: **February 23, 2016**

FIRE DETECTION SYSTEM FUNCTIONAL TESTING

ITEM		YES	NO	COMMENT
1.	Was a complete set of fire alarm documentation available for use during the inspection?		✓	
2.	Are all smoke and heat detectors in place?	N/A		
3.	Are all fire alarm appliances still suitably positioned (i.e. they have not been compromised by any building modifications)?	✓		
4.	Has functional testing been completed on all fire alarm appliances today?		✓	Horn strobe – System Sensor 12Vdc
5.	Were all fire alarm detection appliances free of exposure to fire since the last inspection?	✓		
6.	Did all visual and functional testing of the fire alarm panel and its associated power sources show it to be in good working order?		✓	FAP Type: Vista 32FB Batteries (size, readings and date): [1] 12Vdc 7Ah [undated] Reading: 13.23Vdc 8.30Ah Circuit Breaker: Location: N/A
7.	Did all audible and visual appliances perform properly?		✓	
8.	Did the Central Station receive signals from Fire Alarm Panel events?	N/A		
9.	Were the system and its appliances restored to their normal operational mode and the management notified that the testing was complete?	✓		DSC Cellular Dialer

Recommendations

1. Sounder is broken on keypad, does not sound trouble. Recommend repair or replacement.
2. Waterflow switch is wired incorrectly and will not activate horn strobe. Facility to contact installers and have them correct the wiring. Retest.

PSD	Photoelectric Smoke Detector
ISD	Ionization Smoke Detector
D	Damper
DD	Duct Detector
DHSD	Door Holder Smoke Detector
SSSD	Single Station Smoke Detector
BD	Beam Detector
PS	Pull Station
RRHD	Rate of Rise Heat Detector
HD	Fixed Temp Heat Detector
FD	Flame Detector
FP	Fire Phone
B	Bell
H	Horn
Spk	Speaker
HS	Horn Strobe
S	Strobe
TS	Tamper Switch
W	Waterflow
DH	Door Holder
NC	Nurse Call
ANN	Annunciator
ML	Magnetic Lock
SS	Speaker Strobe

Copy To: **Willoughby Fire Prevention**
 mkocab@willoughbyohio.com

Submit copy
 to insurance agent
 for rate credit

Fire Loss Control, Inc.
590 Pearl Rd. Brunswick OH 44212
Tel: 330-460-6930 Fax: 330-680-5399 info@firelosscontrol.com

Fire Alarm Panel Monitored Appliances

Item #	Device	Floor No.	Location	Zone	Pass	Fail	Comment
1.	W	1	Sprinkler Riser			✓	Incorrectly wired
2.	TS	1	Backflow 1	004			See sprinkler report
3.	TS	1	Backflow 2	005			See sprinkler report
4.	HS	1	Outdoor Riser Room			✓	Unable to test

Comments