



Acquire Fire Protection, Inc.
17012 Kinsman Rd, Middlefield OH 4406
Tel: 440-632-5600 rkaser@acquirefireprotection.com

Annual

Conferred with: **Clark Baker**
Report to: **DeMilta Iron & Scrap**
Street: **3860 Ben Hur Ave.**
City & State: **Willoughby, Ohio 44094**

Fire Loss Control, Inc., #53 52 1003
Inspector: Dan Sammon, #54 52 1624
Inspector: Joe Sammon, #54 18 1823
Date of Inspection: **February 23, 2016**

FIRE DETECTION SYSTEM FUNCTIONAL TESTING

ITEM		YES	NO	COMMENT
1.	Was a complete set of fire alarm documentation available for use during the inspection?		✓	
2.	Are all smoke and heat detectors in place?	✓		Smoke detector mfg & model # System Sensor 2WT-B
3.	Are all fire alarm appliances still suitably positioned (i.e. they have not been compromised by any building modifications)?	✓		Pull Station – Potter Conventional Horn Strobe – 12Vdc System Sensor, outdoor
4.	Has functional testing been completed on all fire alarm appliances today?	✓		
5.	Were all fire alarm detection appliances free of exposure to fire since the last inspection?	✓		
6.	Did all visual and functional testing of the fire alarm panel and its associated power sources show it to be in good working order?	✓		FAP Type: Vista 32FB Batteries (size, readings and date): [1] 12Vdc 7Ah (2016) Reading: 13.25Vdc 7.30Ah Circuit Breaker: #15 Location: Left of FACP
7.	Did all audible and visual appliances perform properly?	✓		
8.	Did the Central Station receive signals from Fire Alarm Panel events?	N/A		
9.	Were the system and its appliances restored to their normal operational mode and the management notified that the testing was complete?	✓		

Recommendations

PSD Photoelectric Smoke Detector
ISD Ionization Smoke Detector
D Damper
DD Duct Detector
DHSD Door Holder Smoke Detector
SSSD Single Station Smoke Detector
BD Beam Detector
PS Pull Station
RRHD Rate of Rise Heat Detector
HD Fixed Temp Heat Detector
FD Flame Detector
FP Fire Phone
B Bell
H Horn
Spk Speaker
HS Horn Strobe
S Strobe
TS Tamper Switch
W Waterflow
DH Door Holder
NC Nurse Call
ANN Annunciator
ML Magnetic Lock
SS Speaker Strobe

Copy To: Willoughby Fire Prevention
mkocab@willoughbyohio.com

Submit copy
to insurance agent
for rate credit

Fire Loss Control, Inc.
590 Pearl Rd. Brunswick OH 44212
Tel: 330-460-6930 Fax: 330-680-5399 info@firelosscontrol.com

Fire Alarm Panel Monitored Appliances

Item #	Device	Floor No.	Location	Zone	Pass	Fail	Comment
1.	W	1	Office, Riser #1	003			See sprinkler report
2.	W	1	Overhead Riser #2	003			See sprinkler report
3.	TS	1	Office Riser	005			See sprinkler report
4.	TS	1	Overhead Riser	005			See sprinkler report
5.	TS	1	Backflow 1	006			See sprinkler report
6.	TS	1	Backflow 2	006			See sprinkler report
7.	PSD	1	Above FACP	001	✓		
8.	PS	1	Below FACP	002	✓		
9.	Keypad	1	Below FACP		✓		
10.	HS	1	Outdoor Riser Room		✓		

Comments:

The smoke detectors and horn strobes in Suites 10 and 11 are not tied into this system.



Acquire Fire Protection, Inc.
17012 Kinsman Rd, Middlefield OH 4406
Tel: 440-632-5600 rkaser@acquirefireprotection.com

Annual

Conferred with: **Clark Baker**
Report to: **DeMilta Iron & Scrap**
Street: **3860 Ben Hur Ave.**
City & State: **Willoughby, Ohio 44094**

Fire Loss Control, Inc., #53 52 1003
Inspector: Dan Sammon, #54 52 1624
Inspector: Joe Sammon, #54 18 1823
Date of Inspection: **February 23, 2016**

FIRE DETECTION SYSTEM FUNCTIONAL TESTING

ITEM		YES	NO	COMMENT
1.	Was a complete set of fire alarm documentation available for use during the inspection?		✓	
2.	Are all smoke and heat detectors in place?	✓		Smoke detector mfg & model # System Sensor 2WT-B
3.	Are all fire alarm appliances still suitably positioned (i.e. they have not been compromised by any building modifications)?	✓		Pull Station – Potter Conventional Horn Strobe – 12Vdc System Sensor, outdoor
4.	Has functional testing been completed on all fire alarm appliances today?	✓		
5.	Were all fire alarm detection appliances free of exposure to fire since the last inspection?	✓		
6.	Did all visual and functional testing of the fire alarm panel and its associated power sources show it to be in good working order?	✓		FAP Type: Vista 32FB Batteries (size, readings and date): [1] 12Vdc 7Ah (2016) Reading: 13.25Vdc 7.30Ah Circuit Breaker: #15 Location: Left of FACP
7.	Did all audible and visual appliances perform properly?	✓		
8.	Did the Central Station receive signals from Fire Alarm Panel events?	N/A		
9.	Were the system and its appliances restored to their normal operational mode and the management notified that the testing was complete?	✓		

Recommendations

PSD Photoelectric Smoke Detector
ISD Ionization Smoke Detector
D Damper
DD Duct Detector
DHSD Door Holder Smoke Detector
SSSD Single Station Smoke Detector
BD Beam Detector
PS Pull Station
RRHD Rate of Rise Heat Detector
HD Fixed Temp Heat Detector
FD Flame Detector
FP Fire Phone
B Bell
H Horn
Spk Speaker
HS Horn Strobe
S Strobe
TS Tamper Switch
W Waterflow
DH Door Holder
NC Nurse Call
ANN Annunciator
ML Magnetic Lock
SS Speaker Strobe

Copy To: **Willoughby Fire Prevention**
mkocab@willoughbyohio.com

Submit copy
to insurance agent
for rate credit

Fire Loss Control, Inc.
590 Pearl Rd. Brunswick OH 44212
Tel: 330-460-6930 Fax: 330-680-5399 info@firelosscontrol.com

Fire Alarm Panel Monitored Appliances

Item #	Device	Floor No.	Location	Zone	Pass	Fail	Comment
1.	W	1	Office, Riser #1	003			See sprinkler report
2.	W	1	Overhead Riser #2	003			See sprinkler report
3.	TS	1	Office Riser	005			See sprinkler report
4.	TS	1	Overhead Riser	005			See sprinkler report
5.	TS	1	Backflow 1	006			See sprinkler report
6.	TS	1	Backflow 2	006			See sprinkler report
7.	PSD	1	Above FACP	001	✓		
8.	PS	1	Below FACP	002	✓		
9.	Keypad	1	Below FACP		✓		
10.	HS	1	Outdoor Riser Room		✓		

Comments:

The smoke detectors and horn strobes in Suites 10 and 11 are not tied into this system.