

Fire Loss Control, Inc.

590 Pearl Road
Brunswick, Ohio 44212

Fire Extinguishers**Service History**

Order # 11497

JOB LOCATION

Solon Park Apartments
34700 Park East Drive, Suite A-101
Solon Ohio 44139
440-349-3800

Service Date: 11/17/2015

CONTACT

Carl

P1: (440)349-3800

P2:

F:

CLIENT

Fire Loss Control
590 Pearl Road
Brunswick Ohio 44212

TECHNICIAN

JAL

Num S/N	Location	Size / Type	Mfg Date	Hydro Test	6 Year	Bar Code	Timestamp
1 YG536126	3051 Maint. shop	5 ABC	2008		2014	AQ0007324	11/17/2015 8:50:56 AM
2 BF578230	Maintenance	5 ABC	2012			BF578230	11/17/2015 8:45:03 AM
3 YG536125	Maintenance	5 ABC	2006		2014	AQ0007327	11/17/2015 8:44:54 AM
4 AX78285	Pool mech rm	5 ABC	2012			AX78285	11/17/2015 1:07:04 PM
5 B04994098	Maint spare	5 ABC	2015			B04994098	11/17/2015 1:54:55 PM
6 A38512204	2:34900 B	5 ABC	2015			A38512204	11/17/2015 9:10:11 AM
7 YT951640	1:3113 34900 B	5 ABC	2007		2013	YT951640	11/17/2015 9:12:24 AM
8 YT951622	2:3116 34900 A	5 ABC	2007		2013	YT951622	11/17/2015 9:17:31 AM
9 CB958680	1:34900 A	5 ABC	2013			CB958680	11/17/2015 9:19:35 AM
10 BF569464	1936 North Garage	5 ABC	2012			BF569464	11/17/2015 9:24:04 AM
11 YT951628	:3114 North Garage	5 ABC	2007		2014	YT951628	11/17/2015 9:55:35 AM
12 YT951595	34850 North Garage	5 ABC	2007		2014	YT951595	11/17/2015 10:19:44 AM
13 A98118806	3052 Middle Garage	5 ABC	2015			A98118805	11/17/2015 11:29:46 AM
14 H796626	:3099 Middle Garage	5 ABC	2009		2015	H796626	11/17/2015 11:08:51 AM
15 AV599418	1527 South garage	5 ABC	2011			AV599418	11/17/2015 12:49:35 PM
16 B04995041	South Garage	5 ABC	2015			B04995041	
17 YT951651	2:3110 34850 B	5 ABC	2007		2013	YT951651	11/17/2015 9:27:45 AM
18 CB957613	1:3109 34850 B	5 ABC	2013			CB957613	11/17/2015 9:29:29 AM
19 CB958677	2:34850 A	5 ABC	2014			CB958677	11/17/2015 9:31:50 AM
20 CB959636	1:34850 A	5 ABC	2013			CB959636	11/17/2015 9:34:56 AM
21 ZK399676	2:3108 34800 B	5 ABC	2008		2014	ZK399676	11/17/2015 9:37:30 AM
22 YT937021	1:3107 34800 B	5 ABC	2007		2013	YT937021	11/17/2015 9:39:19 AM
23 ZK399677	2:3106 34800 A	5 ABC	2008		2014	ZK399677	11/17/2015 9:42:33 AM
24 ZK399687	1:3105 34800 A	5 ABC	2008		2014	ZK399687	11/17/2015 9:44:15 AM
25 YT937004	2:3104 34780 B	5 ABC	2007		2013	YT937004	11/17/2015 9:46:45 AM
26 YT936993	1:3103 34780 B	5 ABC	2007		2013	YT936993	11/17/2015 9:48:52 AM
27 ZK399674	2:3102 34780 A	5 ABC	2008		2014	ZK399674	11/17/2015 9:51:34 AM
28 YT951637	1:3101 34780 A	5 ABC	2007		2013	YT951637	11/17/2015 9:53:22 AM
29 YT937003	2:3097 34755 A	5 ABC	2007		2013	YT937003	11/17/2015 10:09:06 AM

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Fire Loss Control, Inc.

590 Pearl Road
Brunswick, Ohio 44212

Fire Extinguishers**Service History**

Order # 11497

JOB LOCATION

Solon Park Apartments
34700 Park East Drive, Suite A-101
Solon Ohio 44139
440-349-3800

P1: (440)349-3800

P2:

F:

CLIENT

Fire Loss Control
590 Pearl Road
Brunswick Ohio 44212

Num S/N	Location	Size / Type	Mfg Date	Hydro Test	6 Year	Bar Code	Timestamp
30 YT951603	1:3096 34755 A	5 ABC	2007		2013	YT951603	11/17/2015 10:11:17 AM
31 A38508195	2:34755 B	5 ABC	2015			A38508195	11/17/2015 10:14:37 AM
32 ZK399681	1:3094 34755 B	5 ABC	2008		2014	ZK399681	11/17/2015 10:16:29 AM
33 ZK399678	2:3093 34760 B	5 ABC	2008		2014	ZK399678	11/17/2015 10:22:50 AM
34 ZK399682	1:3092 34760 B	5 ABC	2008		2014	ZK399682	11/17/2015 10:24:25 AM
35 H796598	2:3091 34760 A	5 ABC	2009		2015*	H796598	11/17/2015 11:41:46 AM
36 YT951617	1:3090 34760 A	5 ABC	2007		2013	YT951617	11/17/2015 10:28:38 AM
37 YT951623	2:3089 34700 A	5 ABC	2007		2013	YT951623	11/17/2015 10:38:23 AM
38 A34487508	1:3088 34700 A	5 ABC	2014			A34487508	11/17/2015 10:40:21 AM
39 ZK399673	2:3086 34700 B	5 ABC	2008		2014	ZK399673	11/17/2015 10:44:30 AM
40 ZK399675	1:3087 34700 B	5 ABC	2008		2014	ZK399675	11/17/2015 11:42:15 AM
41 YT951655	2:3085 34600 A	5 ABC	2007		2013	YT951655	11/17/2015 10:51:10 AM
42 YT951636	1:3084 34600 A	5 ABC	2007		2013	YT951636	11/17/2015 10:53:53 AM
43 ZK399683	2:3083 34600 B	5 ABC	2008		2014	ZK399683	11/17/2015 10:57:32 AM
44 YT951584	1:3082 34600 B	5 ABC	2007		2013	YT951584	11/17/2015 10:59:15 AM
45 YT951587	2:3081 A34500	5 ABC	2007		2013	YT951587	11/17/2015 11:17:21 AM
46 ZK399684	1:3080 34500 A	5 ABC	2008		2014	ZK399684	11/17/2015 11:19:49 AM
47 YK311180	2:3076 34500 B	5 ABC	2006	2012		YK311180	11/17/2015 11:11:21 AM
48 ZK399646	1:3078 34500 B	5 ABC	2008		2014	ZK399646	11/17/2015 11:13:37 AM
49 A34490495	2:34455 B	5 ABC	2014			A34490495	11/17/2015 11:52:24 AM
50 BL188721	1:3079 34455 B	5 ABC	2012			BL188721	11/17/2015 11:54:19 AM
51 A35019071	2:34455 A	5 ABC	2014			A35019071	11/17/2015 11:57:12 AM
52 YT951610	1:3074 34455 A	5 ABC	2007		2013	YT951610	11/17/2015 11:58:53 AM
53	2:3071 34355 A	5 ABC	1993	2005	2011	AQ0007335	11/17/2015 12:05:57 PM
54 YT951678	1:3070 34355 A	5 ABC	2007		2013	YT951678	11/17/2015 12:07:32 PM
55 A35016042	2:34355 B	5 ABC	2014			A35016042	11/17/2015 12:10:34 PM
56 YT951597	1:3072 34355 B	5 ABC	2007		2013	YT951597	11/17/2015 12:12:01 PM
57 A34487511	3:6549 A	5 ABC	2014			A34487511	11/17/2015 12:14:46 PM
58 YG536123	2:3068 6549 A	5 ABC	2006		2011	AQ0007336	11/17/2015 12:16:39 PM
59 ZK399701	1:3067 6549 A	5 ABC	2008		2014	ZK399701	11/17/2015 12:18:30 PM
60 ZK399679	3:3065 6549 B	5 ABC	2008		2014	ZK399679	11/17/2015 12:20:58 PM

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Fire Loss Control, Inc.

590 Pearl Road
Brunswick, Ohio 44212

Fire Extinguishers**Service History**

Order # 11497

JOB LOCATION

Solon Park Apartments
34700 Park East Drive, Suite A-101
Solon Ohio 44139
440-349-3800

P1: (440)349-3800

P2:

F:

CLIENT

Fire Loss Control
590 Pearl Road
Brunswick Ohio 44212

Num S/N	Location	Size / Type	Mfg Date	Hydro Test	6 Year	Bar Code	Timestamp
61 ZK399645	3:3066 6549 B	5 ABC	2008		2014	ZK399645	11/17/2015 12:23:02 PM
62 BZ311189	1:6549 B	5 ABC	2013			BZ311189	11/17/2015 12:24:49 PM
63 A35017076	2:6539 A	5 ABC	2014			A35017076	11/17/2015 12:35:21 PM
64 H796604	1:3062 6539 A	5 ABC	2009		2015*	H796604	11/17/2015 1:15:29 PM
65 ZK399708	2:3061 6539 B	5 ABC	2008		2014	ZK399708	11/17/2015 12:42:43 PM
66 YT951608	1:3098 6539 B	5 ABC	2007		2012	YT951608	11/17/2015 12:45:08 PM
67 ZK399637	3:3059 34300 A	5 ABC	2008		2014	ZK399637	11/17/2015 1:30:07 PM
68 YT951606	2:3058 34300 A	5 ABC	2007		2013	YT951606	11/17/2015 1:30:51 PM
69 YT951620	1:3057 34300 A	5 ABC	2007		2013	YT951620	11/17/2015 1:32:57 PM
70 CB958679	3:34300 B	5 ABC	2014			CB958679	11/17/2015 1:36:00 PM
71 AX78290	2:1525 34300 B	5 ABC	2012			AX78290	11/17/2015 1:37:58 PM
72 YT951615	1:34300 B	5 ABC	2007		2013	YT951615	11/17/2015 1:39:47 PM
73 AX81266	2:1524 Maint. office	5 ABC	2012			AX81266	11/17/2015 8:47:53 AM
74 BF578232	1935 Phase 1 Garage S	5 ABC	2012			BF578232	*** Missing ***
75 BF569468	:1938 Phase 1 Garage N	5 ABC	2012			BF569468	*** Missing ***
76 BL188712	7658 Maintenance Spare	5 ABC	2012			BL188712	*** Missing ***
77 WF247937	:34850 Garage	5 ABC	2003		2009	AQ0007328	*** Missing ***

Extinguisher Work Summary as of 11/17/2015

	Hydro Test	6 Year	Annual	Monthly	Recharge	New	Monthly	Other	Totals
ABC	0	2	70	0	0	1	0	4	77
Totals	0	2	70	0	0	1	0	4	77

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS