

Fire Loss Control, Inc.590 Pearl Road
Brunswick, Ohio 44212**Fire Extinguishers****Service History**

Order # 11771

JOB LOCATIONEuclid Beach Villa
125 E 156th Street
Cleveland OH 44110
216-531-3820
Service Date: 1/28/2016P1: (216)531-3820
P2:
F: (216)531-8866**CLIENT**Fire Loss Control, Inc.
590 Pearl Road
Brunswick OH 44212**CONTACT**

Elijah Eleazar

(216)531-3820

TECHNICIAN

MRO

| Num S/N | Location | Size / Type | Mfg Date | Hydro Test | 6 Year | Bar Code | Timestamp |
|--------------|------------------------|-------------|----------|------------|--------|-----------|----------------------|
| 1 SS-511836 | 1:0323 computer lab | 5 ABC | 2001 | 2013 | | AQ0008065 | |
| 2 SS-509503 | 1:0324 hall | 5 ABC | 2001 | 2013 | | AQ0008064 | |
| 3 BF578231 | 1:5943 laundry | 5 ABC | 2012 | | | BF578231 | |
| 4 PJ-241101 | 1:0326 hall | 5 ABC | 1997 | 2010 | 2016* | AQ0008067 | |
| 5 NW-708677 | 1:0327 boiler | 5 ABC | 1997 | 2010 | 2016* | NW-708677 | |
| 6 NW-708676 | 1:0328 hall | 5 ABC | 1997 | 2010 | 2016* | NW-708676 | |
| 7 XN-404210 | 1:0329 manager office | 5 ABC | 2006 | | 2012 | AQ0008041 | |
| 8 ZN787518 | 1:kitchen | 5 ABC | 2008 | | 2014 | ZN787518 | |
| 9 PV-915261 | 1:0338 By community rm | 5 ABC | 1999 | 2012 | | AQ0008066 | |
| 10 SS-511823 | 2:0332 hall | 5 ABC | 2001 | 2013 | | AQ0008062 | |
| 11 SM-904809 | 2:0333 hall | 5 ABC | 2001 | 2013 | | AQ0008063 | |
| 12 XC-130438 | 2:0331 hall | 5 ABC | 2005 | | 2011 | AQ0008059 | |
| 13 SS-509510 | 2:0330 hall | 5 ABC | 2001 | 2013 | | AQ0008058 | |
| 14 XC-130500 | 2:0348 elevator | 5 ABC | 2005 | | 2011 | AQ0008060 | |
| 15 XN-404159 | 3:0337 hall | 5 ABC | 2006 | | 2012 | AQ0008054 | |
| 16 XC-127497 | 3:0335 hall | 5 ABC | 2005 | | 2011 | AQ0008055 | |
| 17 SE-946866 | 3:0334 hall | 5 ABC | 2001 | 2013 | | AQ0008061 | |
| 18 SS-509500 | 3:0365 Hall | 5 ABC | 2001 | 2013 | | AQ0008056 | |
| 19 SS-511833 | 3:0383 Hall | 5 ABC | 2001 | 2013 | | AQ0008057 | |
| 20 SS-509508 | 4:0350 hall | 5 ABC | 2001 | 2013 | | AQ0008049 | 1/28/2016 2:01:57 PM |
| 21 RK-239093 | 4:0353 hall | 5 ABC | 2000 | 2012 | | AQ0008048 | |
| 22 XC-130459 | 4:0351 hall | 5 ABC | 2006 | | 2012 | AQ0008050 | |
| 23 SU-505402 | 4:0355 hall | 5 ABC | 2001 | 2013 | | AQ0008051 | |
| 24 SS-511830 | 5:0352 Hall | 5 ABC | 2001 | 2013 | | AQ0008046 | |
| 25 XC-130427 | 5:0340 hall | 5 ABC | 2005 | | 2012 | AQ0008044 | |
| 26 SS-511829 | 5:0341 hall | 5 ABC | 2001 | 2013 | | AQ0008047 | |
| 27 SX-891299 | 5:0399 hall | 5 ABC | | 2010 | 2016* | AQ0008043 | |

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Fire Loss Control, Inc.590 Pearl Road
Brunswick, Ohio 44212**Fire Extinguishers****Service History**

Order # 11771

JOB LOCATIONEuclid Beach Villa
125 E 156th Street
Cleveland OH 44110
216-531-3820P1: (216)531-3820
P2:
F: (216)531-8866**CLIENT**Fire Loss Control, Inc.
590 Pearl Road
Brunswick OH 44212

| Num S/N | Location | Size / Type | Mfg Date | Hydro Test | 6 Year | Bar Code | Timestamp |
|--------------|-----------------|-------------|----------|------------|--------|-----------|----------------------|
| 28 RR-504197 | 5:0354 elevator | 5 ABC | 2000 | 2012 | | AQ0008045 | |
| 29 SU-505410 | 6:7921 hall | 5 ABC | 2000 | 2013 | | AQ0008037 | |
| 30 XC-128867 | 6:0343 hall | 5 ABC | 2005 | | 2011 | AQ0008038 | |
| 31 KR-841092 | 6:0397 hall | 5 ABC | 1992 | 2010 | 2016* | AQ0008036 | |
| 32 PJ-243020 | 6:0400 hall | 5 ABC | 1997 | 2010 | 2016* | AQ0008040 | |
| 33 XC-127480 | 6:0398 elevator | 5 ABC | 2005 | | 2011 | AQ0008039 | |
| 34 SS-511849 | 7:0356 hall | 5 ABC | 2001 | 2013 | | AQ0008042 | |
| 35 SS-511818 | 7:0358 hall | 5 ABC | 2001 | 2013 | | AQ0008034 | |
| 36 SS-511850 | 7:0359 hall | 5 ABC | 2001 | 2013 | | AQ0008035 | |
| 37 BF578233 | 7:6194 elevator | 5 ABC | 2012 | | | BF578233 | |
| 38 SS-511827 | 7:0357 hall | 5 ABC | 2001 | 2013 | | AQ0008033 | |
| 39 SS-511824 | 8:0373 Hall | 5 ABC | 2001 | 2013 | | AQ0008030 | |
| 40 PJ-243021 | 8:0360 hall | 5 ABC | 1997 | 2010 | 2016* | AQ0008032 | |
| 41 SS-511831 | 8:0363 elevator | 5 ABC | 2001 | 2013 | | AQ0008029 | 1/28/2016 1:55:43 PM |
| 42 SS-511825 | 8:0361 hall | 5 ABC | 2001 | 2013 | | AQ0008031 | |
| 43 ZN788786 | 8:6385 hall | 5 ABC | 2009 | | 2015 | ZN788786 | |
| 44 SS-511828 | 9:0366 hall | 5 ABC | 2001 | 2013 | | AQ0008024 | |
| 45 SU-505396 | 9:0367 hall | 5 ABC | 2001 | 2013 | | AQ0008025 | |
| 46 PJ-243005 | 9:0368 elevator | 5 ABC | 1997 | 2010 | 2016* | AQ0008026 | |
| 47 SS-511841 | 9:0369 hall | 5 ABC | 2001 | 2013 | | AQ0008027 | |
| 48 BF569465 | 9:6193 hall | 5 ABC | 2012 | | | BF569465 | |
| 49 SS-511817 | 10:0371 hall | 5 ABC | 2001 | 2013 | | AQ0008020 | |
| 50 SS-511832 | 10:0372 hall | 5 ABC | 2001 | 2013 | | AQ0008021 | |
| 51 XN-404211 | 10:beauty shop | 5 ABC | 2006 | 2013 | | AQ0008070 | |
| 52 NW-708680 | 10:0374 hall | 5 ABC | 1997 | 2010 | 2016* | NW-708680 | |
| 53 SS-511851 | 10:0375 hall | 5 ABC | 2001 | 2013 | | AQ0008023 | |
| 54 SS-509504 | 10:0347 Hall | 5 ABC | 2001 | 2013 | | AQ0008022 | 1/28/2016 1:56:47 PM |
| 55 SE-946865 | 11:0370 Hall | 5 ABC | 2001 | 2013 | | AQ0008018 | |
| 56 SS-509514 | 11:0377 hall | 5 ABC | 2001 | 2013 | | AQ0008015 | |
| 57 XC-130415 | 11:0379 hall | 5 ABC | 2005 | | 2011 | AQ0008016 | |
| 58 SS-511826 | 11:0380 hall | 5 ABC | 2001 | 2013 | | AQ0008017 | |

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Fire Loss Control, Inc.590 Pearl Road
Brunswick, Ohio 44212**Fire Extinguishers****Service History**

Order # 11771

JOB LOCATIONEuclid Beach Villa
125 E 156th Street
Cleveland OH 44110
216-531-3820P1: (216)531-3820
P2:
F: (216)531-8866**CLIENT**Fire Loss Control, Inc.
590 Pearl Road
Brunswick OH 44212

| Num S/N | Location | Size / Type | Mfg Date | Hydro Test | 6 Year | Bar Code | Timestamp |
|--------------|---------------------------|-------------|----------|------------|--------|-----------|-----------------------|
| 59 TB155897 | 11:Hall ### | 5 ABC | 2003 | 2015 | | TB155897 | |
| 60 PJ-242966 | 12:0381 hall | 5 ABC | 1997 | 2010 | 2016* | AQ0008013 | |
| 61 BF568793 | 12:6191 hall eleva. | 5 ABC | 2012 | | | | |
| 62 MP-560645 | 12:0384 hall | 5 ABC | 1994 | 2010 | 2016* | MP-560645 | |
| 63 RR-504247 | 12:0385 hall | 5 ABC | 2000 | 2012 | | AQ0008012 | |
| 64 PV-915214 | 12:0382 hall | 5 ABC | 1999 | 2011 | | AQ0008011 | |
| 65 PV-915255 | 14:0386 hall | 5 ABC | 1999 | 2013 | | AQ0008009 | |
| 66 SS-509507 | 14:0388 elevator | 5 ABC | 2001 | 2013 | | AQ0008008 | |
| 67 NW-708625 | 14:0389 hall | 5 ABC | 1997 | 2010 | 2016* | NW-708625 | |
| 68 NW-691624 | 14:0390 hall | 5 ABC | 1997 | 2010 | 2016* | NW-691624 | |
| 69 XC-130440 | 14:0387 hall | 5 ABC | 2005 | | 2011 | AQ0008010 | |
| 70 JR-971229 | 15:0391 hall | 5 ABC | 1990 | 2010 | 2011 | AQ0008007 | |
| 71 SS-509511 | 15:0393 elevator | 5 ABC | 2001 | 2013 | | AQ0008006 | |
| 72 NW-691623 | 15:0394 hall | 5 ABC | 1997 | 2010 | 2016* | NW-691623 | |
| 73 NW-708622 | 15:0395 hall | 5 ABC | 1997 | 2010 | 2016* | NW-708622 | |
| 74 NW-708674 | 15:0392 hall | 5 ABC | 1997 | 2010 | 2016* | NW-708674 | |
| 75 | 16:0402 hall | 5 ABC | 1988 | 2010 | 2016* | AQ0008001 | |
| 76 SS-511834 | 16:0403 hall | 5 ABC | 2001 | 2013 | | AQ0008002 | |
| 77 SS-509499 | 16:0404 elevator | 5 ABC | 2001 | 2013 | | AQ0008003 | |
| 78 No Label | 16:0405 hall | 5 ABC | 1997 | 2010 | 2016* | AQ0008005 | |
| 79 SS-509501 | 16:0406 hall | 5 ABC | 2001 | 2013 | | AQ0008004 | |
| 80 PV-04284 | 16:spare | 5 ABC | 1998 | 2012 | | AQ0008052 | 1/28/2016 10:30:33 AM |
| 81 CB959186 | 16:Spare | 5 ABC | 2014 | | | CB959186 | 1/28/2016 9:21:00 AM |
| 82 RR-504186 | 16:0396 Spare | 5 ABC | 2000 | 2012 | | AQ0008068 | 1/28/2016 1:59:52 PM |
| 83 CB959634 | 16:Spare | 5 ABC | 2014 | | | CB959634 | 1/28/2016 9:39:31 AM |
| 84 CB959174 | 16:Spare | 5 ABC | 2014 | | | CB959174 | 1/28/2016 10:33:43 AM |
| 85 BF566787 | 16:6192 spare | 5 ABC | 2012 | | | BF566787 | 1/28/2016 1:54:03 PM |
| 86 SS- | 16:0376 Spare | 5 ABC | 2001 | 2013 | | AQ0008014 | 1/28/2016 1:57:37 PM |
| 87 SU-505399 | 16:0378 Spare | 5 ABC | 2001 | 2013 | | AQ0008069 | 1/28/2016 2:01:01 PM |
| 88 PJ-439244 | 17:0362 eleva. mech rm | 5 ABC | 1997 | 2010 | 2016* | PJ-439244 | |

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Fire Loss Control, Inc.590 Pearl Road
Brunswick, Ohio 44212**Fire Extinguishers****Service History**

Order # 11771

JOB LOCATIONEuclid Beach Villa
125 E 156th Street
Cleveland OH 44110
216-531-3820

P1: (216)531-3820

P2:

F: (216)531-8866

CLIENTFire Loss Control, Inc.
590 Pearl Road
Brunswick OH 44212

| Num S/N | Location | Size / Type | Mfg Date | Hydro Test | 6 Year | Bar Code | Timestamp |
|---------|------------|-------------|----------|------------|--------|----------|-----------------|
| 89 | 0401 Spare | 5 ABC | 1985 | 2010 | * | | *** Missing *** |

Extinguisher Work Summary as of 1/28/2016

| | Hydro Test | 6 Year | Annual | Monthly | Recharge | New | Monthly | Other | Totals |
|--------|------------|--------|--------|---------|----------|-----|---------|-------|--------|
| ABC | 0 | 19 | 68 | 0 | 1 | 0 | 0 | 1 | 89 |
| Totals | 0 | 19 | 68 | 0 | 1 | 0 | 0 | 1 | 89 |

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS