

Acquire Fire Protection, Inc.17012 Kinsman Road
Middlefield, Ohio 44062**Fire Suppression Systems****Service History**

Order # 11899

JOB LOCATIONR Place Grill
15561 Kinsman Rd Unit 12
Middlefield OH 44062
440-497-7667

Service Date: 1/26/2016

CONTACT

John

P1:

P2:

F:

(440)497-7667

CLIENTR Place Grill
15561 Kinsman Rd Unit 12
Middlefield Ohio 44062**TECHNICIAN**

JAL

Fire Suppression System

Num: 1

Type: Dry Chemical Extinguishing System

Manufacturer: Kidde

Model:

Location: Kitchen

Install Date:

Last Service: 1/2016

Duct Size: 14" round

Plenum Size: 10" x 6ft

Serial #:

Bar Code:

Timestamp:

Nozzle Type:

Nozzle Type:

Tests/Inspections/Services

Description	Last	Due
Hydro Test	2011	☐
6 Year		☐
Monthly		☐
Recharge		☐
Semi-Annual	1/2016	☒
New		☐

Cylinders

Num	Size	Type	Mfg Date	Hydro	6 Year	S/N	Bar Code	Timestamp
-----	------	------	----------	-------	--------	-----	----------	-----------

Replacement Parts

Qty	Description	Part No.	Replaced
3	Fuse Links 360°F Globe ML	G360ML	1/26/2016

Appliances (Left to Right)

Num	Description	Size	Nozzle(s)
1	Fryer - Elec		Cyclone

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Printed on: 2/8/2016 10:27:16 AM

Acquire Fire Protection, Inc.

17012 Kinsman Road
Middlefield, Ohio 44062

Fire Suppression Systems**Service History**

Order # 11899

JOB LOCATION

R Place Grill
15561 Kinsman Rd Unit 12
Middlefield OH 44062
440-497-7667

CLIENT

R Place Grill
15561 Kinsman Rd Unit 12
Middlefield Ohio 44062

Num	Description	Size	Nozzle(s)
2	Grill - 36"		Cyclone, Cyclone

INSPECTION**I. Fire Suppression Systems**

	Yes	No	NA
1. System cylinder gauge in operable range?	☒	☐	☐
2. Cylinder weight OK?	☒	☐	☐
3. Actuation cartridge weight or gauge in operable range?	☐	☐	☒
4. Fusible links replaced?	☒	☐	☐
5. Complete fuel shut-down operational?	☒	☐	☐
6. Remote pull station accessible and operational?	☒	☐	☐
7. All components clean and free of overspray?	☐	☐	☒
8. Nozzle caps cleaned or replaced?	☒	☐	☐
9. System meets manufacturer installation instructions?	☒	☐	☐
/* System is no longer compliant for use in kitchen exhaust hoods */			
10. System conduit and piping securely mounted?	☒	☐	☐
11. Employees trained in the proper operation of the system?	☒	☐	☐
12. Audible and/or visual alarms functional?	☐	☒	☐
13. System reset and placed back in service?	☒	☐	☐
14. System connected to central station?	☐	☒	☐
15. State of Ohio Certification # 53-28-1034	☒	☐	☐
16. State of Ohio Certification Jon LeRoy 54-18-1535	☒	☐	☐
17. State of Ohio Certification James Stauffer 54-43-1824	☐	☐	☒
18. Complete Hydrostatic Pressure Test Current	☒	☐	☐
19. Complete 6 Year Maintenance Current	☒	☐	☐

I state that the information on this form is correct at the time and place of my inspection. And that all equipment tested at this time was left in operational condition upon completion of this inspection except as noted above.

Acquire Fire Protection Inc,
17012 Kinsman Road
Middlefield, Ohio 44062
1-877-443-5532

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Printed on: 2/8/2016 10:27:16 AM

Acquire Fire Protection, Inc.

17012 Kinsman Road
Middlefield, Ohio 44062

Fire Suppression Systems**Service History**

Order # 11899

JOB LOCATION

R Place Grill
15561 Kinsman Rd Unit 12
Middlefield OH 44062
440-497-7667

P1:

P2:

F:

CLIENT

R Place Grill
15561 Kinsman Rd Unit 12
Middlefield Ohio 44062

Technician

X 

Jon LeRoy

1/26/2016

Customer Signature

X _____

Fire Inspector

X _____

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Printed on: 2/8/2016 10:27:16 AM