

Fire Loss Control, Inc.590 Pearl Road
Brunswick, Ohio 44212**Fire Extinguishers****Service History**

Order # 11650

JOB LOCATIONTrelleborg Wheel
1501 Exeter Road
Akron Ohio 44306P1: (330)993-0054
P2:
F:**CLIENT**Fire Loss Control, Inc.
590 Pearl Road
Brunswick Ohio 44212

Service Date: 12/21/2015

CONTACT

Ron Green

TECHNICIAN

JAL

Num S/N	Location	Size / Type	Mfg Date	Hydro Test	6 Year	Bar Code	Timestamp
1 S394816	At Ramp	10 ABC	2010			S394816	12/21/2015 12:05:44 PM
2 A38279422	Top of Ramp	10 ABC	2014			A38279422	12/21/2015 12:06:24 PM
3 A38268889	Ramp door 32	10 ABC	2014			A38268889	12/21/2015 12:07:51 PM
4 A38267398	P 27	10 ABC	2014			A38267398	12/21/2015 11:58:20 AM
5 ZT423163	P 25	10 ABC	2008		2014	ZT423163	12/21/2015 11:55:58 AM
6 ZT433600	Dock 33	10 ABC	2009		2015*	ZT433600	12/21/2015 2:43:42 PM
7 ZT425418	E employ entry	10 ABC	2008		2014	ZT425418	12/21/2015 3:16:52 PM
8 ZT433636	Cleaning supplies	10 ABC	2009		2015*	ZT433636	12/21/2015 3:49:15 PM
9 ZT433472	S office at time clock	10 ABC	2009		2015*	ZT433472	12/21/2015 2:44:39 PM
10 H427856	Office	5 ABC	2009		2015*	H427856	12/21/2015 2:44:28 PM
11 BK153064	Office	5 ABC	2012			BK153064	12/21/2015 11:51:05 AM
12 N145596	Dock 36	10 ABC	2009		2015*	N145596	12/21/2015 2:46:12 PM
13 ZT425419	Dock 39	10 ABC	2008		2014	ZT425419	12/21/2015 11:46:14 AM
14 ZX517546	S 21	10 ABC	2009		2015*	ZX517546	12/21/2015 2:46:55 PM
15 N145600	P 23	10 ABC	2009		2015*	N145600	12/21/2015 2:49:29 PM
16 ZT426913	P 19	10 ABC	2008		2014	ZT426913	12/21/2015 11:54:30 AM
17 ZT425427	S 17	10 ABC	2008		2014	ZT425427	12/21/2015 11:36:30 AM
18 A38279424	mez:So end	10 ABC	2014			A38279424	12/21/2015 11:39:34 AM
19 C873530	mez:So.end hall	10 ABC	2009		2015*	C873530	12/21/2015 2:47:30 PM
20 GJ-719476	mez:Centre mez U 27	10 ABC	1986	2010		AQ0008945	12/21/2015 11:41:08 AM
21 ZT425431	mez:No. Mez U 29	10 ABC	2008		2014	ZT425431	12/21/2015 11:43:11 AM
22 ZT433485	L 25	10 ABC	2009		2015*	ZT433485	12/21/2015 3:04:57 PM
23 B02530937	L 23	10 ABC	2015			B02530937	12/21/2015 2:39:36 PM
24 C871024	L 17	10 ABC	2009		2015*	C871024	12/21/2015 3:03:04 PM
25 A38265465	E 17 Maint. area	10 ABC	2014			A38265465	12/21/2015 1:07:08 PM
26 NM-508311	Spare	10 ABC	1996	2008	2014	NM-508311	12/21/2015 1:10:34 PM
27 PX-133085	Spare	5 ABC	1998	2013		PX-133085	12/21/2015 1:08:32 PM
28 R984066	Spare	5 ABC	2009		2015*	R984066	12/21/2015 3:02:02 PM
29 N145566	C 19 at Maint.	10 ABC	2009		2015*	N145566	12/21/2015 3:00:33 PM

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Fire Loss Control, Inc.590 Pearl Road
Brunswick, Ohio 44212**Fire Extinguishers****Service History**

Order # 11650

JOB LOCATIONTrelleborg Wheel
1501 Exeter Road
Akron Ohio 44306

P1: (330)993-0054

P2:

F:

CLIENTFire Loss Control, Inc.
590 Pearl Road
Brunswick Ohio 44212

Num S/N	Location	Size / Type	Mfg Date	Hydro Test	6 Year	Bar Code	Timestamp
30 A27520177	C 19 At chargers	10 ABC	2014			A27520177	12/21/2015 12:36:52 PM
31 N145601	A 19 Rim shop	10 ABC	2009		2015*	N145601	12/21/2015 2:59:25 PM
32 ZT433584	Employee entry	10 ABC	2009		2015*	ZT433584	12/21/2015 2:59:43 PM
33 ZT433492	Break room	10 ABC	2009		2015*	ZT433492	12/21/2015 3:50:55 PM
34 N145525	Wheel workshop	10 ABC	2009		2015*	N145525	12/21/2015 2:58:38 PM
35 ZT433481	C 21	10 ABC	2009		2015*	ZT433481	12/21/2015 2:58:10 PM
36 ZT433489	Lab	10 ABC	2009		2015*	ZT433489	12/21/2015 2:55:43 PM
37 ZT425423	Office entry	10 ABC	2008		2014	ZT425423	12/21/2015 3:08:26 PM
38 ZT433476	Main office	10 ABC	2009		2015*	ZT433476	12/21/2015 3:48:06 PM
39 ZT433586	Office kitchen	10 ABC	2009		2015*	ZT433586	12/21/2015 3:47:51 PM
40 A27520178	C 25	10 ABC	2014			A27520178	12/21/2015 12:29:37 PM
41 N145593	E 27	10 ABC	2009		2015*	N145593	12/21/2015 2:54:55 PM
42 ZT425445	G 25	10 ABC	2008		2014	ZT425445	12/21/2015 1:04:29 PM
43 ZT433622	G 27	10 ABC	2009		2015*	ZT433622	12/21/2015 2:54:11 PM
44 ZT426915	G 29	10 ABC	2008		2014	ZT426915	12/21/2015 12:26:02 PM
45 A27526105	31 at OH	10 ABC	2014			A27526105	12/21/2015 12:10:11 PM
46 A27520171	L 33	10 ABC	2014			A27520171	12/21/2015 12:12:57 PM
47 A38267404	L 37	10 ABC	2014			A38267404	12/21/2015 12:15:13 PM
48 XT869307	L 39	10 ABC	2006		2014	XT869307	12/21/2015 12:22:04 PM
49 A27520181	L 41	10 ABC	2014			A27520181	12/21/2015 12:22:25 PM
50 ZT425429	:G 41	10 ABC	2008		2014	ZT425429	12/21/2015 12:19:46 PM
51 KZ-303941	G 35	10 ABC	1993	2005	2011	KZ-303941	12/21/2015 12:23:39 PM

Extinguisher Work Summary as of 12/21/2015

	Hydro Test	6 Year	Annual	Monthly	Recharge	New	Monthly	Other	Totals
ABC	0	22	28	0	0	1	0	0	51
Totals	0	22	28	0	0	1	0	0	51

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS