

**Fire Loss Control, Inc.**590 Pearl Road  
Brunswick, Ohio 44212**Fire Extinguishers****Service History**

Order # 12018

**JOB LOCATION**Wickliffe Country Place  
1919 Bishop Rd  
Wickliffe Ohio 44092  
Chris Manuel  
440-944-9400  
Service Date: 3/18/2016P1: (440)944-9400  
P2:  
F:**CLIENT**Fire Loss Control, Inc.  
590 Pearl Road  
Brunswick Ohio 44212**CONTACT**

Chris

**TECHNICIAN**

JAL

Num S/N	Location	Size / Type	Mfg Date	Hydro Test	6 Year	Bar Code	Timestamp
1 PS-295241	LL:800 Cold Storage	5 ABC	1998	2010	2016*	AQ0008314	3/18/2016 10:36:17 AM
2 XR910423	LL:1034 Hall at Cold storage	5 ABC	2006	2016*		XR910423	3/18/2016 10:44:40 AM
3 CB957623	LL:Enviro. Services	5 ABC	2014			CB957623	3/18/2016 8:35:46 AM
4 TC-067318	LL hy:7787 Hall at Central Supply	5 ABC	2002	2015		AQ0008283	3/18/2016 8:37:49 AM
5 YM555428	LL:7789 Central supply	10 ABC	2007		2013	YM555428	3/18/2016 8:39:01 AM
6 PV-674916	LL:1029 Employee Break rm	5 ABC	1998	2010	2016*	AQ0008312	3/18/2016 10:33:37 AM
7 XF215347	LL:1027 HR Storeroom	10 ABC	2005		2011	XF215347	3/18/2016 11:25:42 AM
8 YK188333	LL:1030 Boiler room	10 ABC	2007		2013	YK188333	3/18/2016 8:50:10 AM
9 YM555487	LL:1026 Laundry	10 ABC	2007	2013		YM555487	3/18/2016 8:52:43 AM
10 E589626	LL:799 Hall by PT	10 ABC	2009		2015	E589626	3/18/2016 8:54:12 AM
11 E591405	LL:1025 Elevator rm	10 ABC	2009		2015	E591405	3/18/2016 10:08:42 AM
12 SH889430	1036 Hall A wing	10 ABC	2001	2013		SH889430	3/18/2016 8:59:31 AM
13 YK189345	1037 A Wing exit	10 ABC	2007		2013	YK189345	
14 B08267020	A Wing 108	10 ABC	2016			B08267020	3/18/2016 9:04:40 AM
15 YM562203	790 Dining rm	10 ABC	2007		2013	YM562203	3/18/2016 9:07:05 AM
16 V-733584	1:791 Kitchen	6Liter Class K	1998	2013		V-733584	3/18/2016 11:07:25 AM
17 B04730710	1:B Wing 203	10 ABC	2016			B04730710	3/18/2016 9:08:50 AM
18 CG596320	B Wing 212	10 ABC	2014			CG596320	3/18/2016 9:10:48 AM
19 B13698388	C wing 303	10 ABC	2016			B13698388	3/18/2016 9:13:58 AM
20 F941897	1:792 C wing 312	10 ABC	2009		2015	F941897	3/18/2016 9:15:31 AM
21 YM555466	793 Admin office	10 ABC	2007		2013	YM555466	3/18/2016 9:18:03 AM
22 B04729912	1:D wing 417	10 ABC	2016			B04729912	3/18/2016 9:21:21 AM
23 F945954	1:1020 D wing 403	10 ABC	2009		2015	F945954	3/18/2016 9:22:53 AM
24 SK-841606	1:Recption desk	5 ABC				SK-841606	3/18/2016 9:28:44 AM
25 SH906053	1:1021 Living rm	10 ABC	2001	2013		SH906053	
26 RX-179533	1:1023 Living rm	5 ABC	2000	2013		RX-179533	3/18/2016 9:30:15 AM

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

**Fire Loss Control, Inc.**

590 Pearl Road  
Brunswick, Ohio 44212

**Fire Extinguishers**

**Service History**

Order # 12018

**JOB LOCATION**

Wickliffe Country Place  
1919 Bishop Rd  
Wickliffe Ohio 44092  
Chris Manuel  
440-944-9400

P1: (440)944-9400  
P2:  
F:

**CLIENT**

Fire Loss Control, Inc.  
590 Pearl Road  
Brunswick Ohio 44212

Num S/N	Location	Size / Type	Mfg Date	Hydro Test	6 Year	Bar Code	Timestamp
27 B04730336	1:E Wing 503	10 ABC	2016			B04730336	3/18/2016 9:32:40 AM
28 YM555473	1:794 E Wing 512	10 ABC	2007		2013	YM555473	
29 SH889427	1:797 E Wing Boiler rm	10 ABC	2001	2013		SH889427	3/18/2016 9:39:22 AM
30 YM555429	1:798 D Wing Boiler rm	10 ABC	2007		2013	YM555429	3/18/2016 9:42:52 AM
31 JY-00707030	1:796 C Wing Boiler rm	5 ABC	1991	2016*		AQ10058	3/18/2016 9:54:30 AM
32 WD898878	1:1033 B Wing Boiler rm	5 ABC	2004	2016*		WD898878	3/18/2016 10:45:49 AM
33 WY116065	1:1019 Kitchen Delivery entry	10 ABC	2005		2011	WY116065	3/18/2016 10:00:01 AM
34 XF215325	1:1035 A Wing Boiler rm	10 ABC	2005		2011	XF215325	3/18/2016 10:04:12 AM
35 SK-841289	LL:1022 Van	5 ABC	2001	2013		SK-841289	3/18/2016 11:00:42 AM
36 A40967662	Bus	2.5 ABC	2015			A40967662	
37 AB398088	LL:1028 Spare	6 Liter Class K	2007	2013		AB398088	3/18/2016 11:18:40 AM
38 YS364284	LL:1031 Maintenance	5 ABC	2007		2014	YS364284	3/18/2016 11:16:04 AM
39 XF215327	1:1024 Maintenance	10 ABC	2005		2011	XF215327	3/18/2016 11:14:43 AM
40 YM555446	LL:1150 Maintenance	10 ABC	2007		2013	YM555446	3/18/2016 11:12:27 AM
41 SH-548012	LL:Maintenance	5 ABC	2001	2013		SH-548012	3/18/2016 11:16:30 AM
42 E-335495	LL:7788 Maintenance	5 ABC	2009		2016*	E-335495	3/18/2016 11:32:55 AM

Extinguisher Work Summary as of 3/18/2016

	Hydro Test	6 Year	Annual	Monthly	Recharge	New	Monthly	Other	Totals
ABC	3	3	34	0	0	0	0	0	40
Class K	0	0	2	0	0	0	0	0	2
Totals	3	3	36	0	0	0	0	0	42

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

**Fire Loss Control, Inc.**

590 Pearl Road  
Brunswick, Ohio 44212

**Fire Extinguishers**

**Service History**

Order # 12018

**JOB LOCATION**

Wickliffe Country Place  
1919 Bishop Rd  
Wickliffe Ohio 44092  
Chris Manuel  
440-944-9400

P1: (440)944-9400

P2:

F:

**CLIENT**

Fire Loss Control, Inc.  
590 Pearl Road  
Brunswick Ohio 44212

**Exhibits**

---

1919 Bishop Rd, Wickliffe Ohio 44092, Chris Manuel, 440- FE

3/17/2016 7:41:17 PM

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS