Fire Loss Control, Inc.
590 Pearl Road
Brunswick, Ohio 44212

Fire Suppression Systems
Service History
Order # 11586

JOB LOCATION
Suburban Pavilion
20265 Emery Road
North Randall Ohio 44128
216-475-8880
P2:
F:
Service Date: 11/4/2015

CLIENT
Fire Loss Control, Inc.
590 Pearl Road
Brunswick Ohio 44212

CONTACT
Tom Slivka

TECHNICIAN
JAL

Fire Suppression System

Num: 1
Type: Wet Chemical Extinguishing System
Manufacturer: Ansul
Model: R-102 3 Gallon
Location: Kitchen Oven hood
Install Date: 1994
Last Service: 11/4/2015
Duct Size: 10" X 18
Plenum Size: 18" X 6Ft
Serial #: R 99025
Bar Code: AQ0007221
Timestamp:
Nozzle Type: 2W
Nozzle Type: 1N

Tests/Inspections/Services

Description	Last	Due
Hydro Test	2012	☐
Monthly		☐
Recharge		☐
Semi-Annual	11/2015	☑
Flush Piping		☐
New		☐

Cylinders

Num	Size	Type	Mfg Date	Hydro	6 Year	S/N	Bar Code	Timestamp
1	3 Gal.	Extinguishing Agent	2012	2012		20120604182	AQ0007222	11/7/2013 3:35:19 PM

Replacement Parts

Qty	Description	Part No.	Replaced
1	Fuse Links 360°F K Link	360K-11	11/2015
1	Fuse Links 450°F K Link	450K-11	5/4/2015

Appliances (Left to Right)

Num	Description	Size	Nozzle(s)

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Fire Loss Control, Inc.
590 Pearl Road
Brunswick, Ohio 44212

Fire Suppression Systems
Service History
Order # 11586

JOB LOCATION
Suburban Pavilion
20265 Emery Road
North Randall Ohio 44128
216-475-8880
P2:
F:

CLIENT
Fire Loss Control, Inc.
590 Pearl Road
Brunswick Ohio 44212

Num	Description	Size	Nozzle(s)
1		Plenum & Duct Only	

INSPECTION

I. Fire Suppression Systems	OK	FAIL	NA
1. Hood and appliances properly protected?	☑	☐	☐
2. Was nozzle/appliance alignment correct upon arrival?	☑	☐	☐
If not was the alignemt corrected during inspection?			
3. System cylinder gauge in operable range?	☐	☐	☑
4. Cylinder weight or liquid level OK?	☑	☐	☐
5. Fusible links replaced?	☑	☐	☐
6. Actuation cartridge weight or gauge in operable range?	☑	☐	☐
/* Stamped weight 41 5/8 oz, Actual weight 41 3/4 oz */			
7. Complete fuel shut-down operational?	☑	☐	☐
8. Remote pull station accessible and operational?	☑	☐	☐
9. All components clean and free of grease?	☑	☐	☐
10. Nozzle caps cleaned or replaced?	☑	☐	☐
11. System meets manufacturer installation instructions?	☑	☐	☐
12. System conduit and piping securely mounted?	☑	☐	☐
13. Does system meet UL 300 standard?	☑	☐	☐
14. Employees trained in the proper operation of the system?	☑	☐	☐
15. Audible and/or visual alarms functional?	☑	☐	☐
16. System reset and placed back in service?	☑	☐	☐
17. System connected to central station?	☑	☐	☐
18. Class K extinguisher present and functional?	☑	☐	☐
19. Do hood and duct comply with NFPA #96?	☑	☐	☐
20. Company State of Ohio Certification # 53-28-1034	☑	☐	☐
21. State of Ohio Certification Jon LeRoy 54-18-1535	☑	☐	☐
22. State of Ohio Certification Randolph N Kaser 54-18-0381	☐	☐	☑
23. Complete Hydrostatic Pressure Test Current	☑	☐	☐
24. Complete 6 Year Maintenance Current	☐	☐	☑

I state that the information on this form is correct at the time and place of my inspection. And that all equipment tested at this time was left in operational condition upon completion of this inspection except as noted above.

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Fire Loss Control, Inc.
590 Pearl Road
Brunswick, Ohio 44212

Fire Suppression Systems
Service History
Order # 11586

JOB LOCATION
Suburban Pavilion
20265 Emery Road
North Randall Ohio 44128
216-475-8880
P2:
F:

CLIENT
Fire Loss Control, Inc.
590 Pearl Road
Brunswick Ohio 44212

INSPECTION

I. Fire Suppression Systems OK FAIL NA

Acquire Fire Protection, Inc. / Fire Loss Control, Inc.

Technician

X 

Jonathan LeRoy 11/4/2015

Fire Inspector

X _____

Customer Signature

X _____

*** End Report: 1 ***

Fire Loss Control, Inc.
590 Pearl Road
Brunswick, Ohio 44212

Fire Suppression Systems
Service History
Order # 11586

JOB LOCATION
Suburban Pavilion
20265 Emery Road
North Randall Ohio 44128
216-475-8880
P2:
F:
Service Date: 11/4/2015

CLIENT
Fire Loss Control, Inc.
590 Pearl Road
Brunswick Ohio 44212

CONTACT
Tom Slivka

TECHNICIAN
JAL

Fire Suppression System

Num: 2
Type: Wet Chemical Extinguishing System
Manufacturer: Ansul
Model: R-102 6 Gallon
Location: Kitchen Main
Install Date: 1997
Last Service: 11/4/2015
Duct Size: 2 - 12" X 20"
Plenum Size: 2 - 11Ft
Serial #: R 427562
Bar Code: AQ0007225
Timestamp:
Nozzle Type: 2 -2W
Nozzle Type: 4 -1N

Tests/Inspections/Services

Description	Last	Due
Hydro Test	2007	☐
Monthly		☐
Recharge		☐
Semi-Annual	11/2015	☑
Flush Piping		☐
New		☐

Cylinders

Num	Size	Type	Mfg Date	Hydro	6 Year	S/N	Bar Code	Timestamp
1	3 Gal.	Extinguishing Agent	2007	2007		N/A	AQ0007224	11/7/2013 3:48:02 PM
2	3 Gal	Extinguishing Agent	2007	2007		N/A	AQ0007223	11/7/2013 3:48:31 PM

Replacement Parts

Qty	Description	Part No.	Replaced
4	Fuse Links 450°F K Link	450K-11	11/2015

Appliances (Left to Right)

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Fire Loss Control, Inc.
590 Pearl Road
Brunswick, Ohio 44212

Fire Suppression Systems
Service History
Order # 11586

JOB LOCATION
Suburban Pavilion
20265 Emery Road
North Randall Ohio 44128
216-475-8880
P2:
F:

CLIENT
Fire Loss Control, Inc.
590 Pearl Road
Brunswick Ohio 44212

Num	Description	Size	Nozzle(s)
1	Tilt Skillet		245, 245
2	Range - 6 Burner		3 -1F
3	Grill - 24"		230
4	Char broiler Gas Radiant		1N
5	Fryer - Gas		230

INSPECTION

I. Fire Suppression Systems	OK	FAIL	NA
1. Hood and appliances properly protected?	☑	☐	☐
2. Was nozzle/appliance alignment correct upon arrival?	☑	☐	☐
If not was the alignemt corrected during inspection?			
3. System cylinder gauge in operable range?	☐	☐	☑
4. Cylinder weight or liquid level OK?	☑	☐	☐
5. Fusible links replaced?	☑	☐	☐
6. Actuation cartridge weight or gauge in operable range?	☑	☐	☐
/* Stamped weight 60 7/8 oz, Actual weight 61 oz */			
7. Complete fuel shut-down operational?	☑	☐	☐
8. Remote pull station accessible and operational?	☑	☐	☐
9. All components clean and free of grease?	☑	☐	☐
10. Nozzle caps cleaned or replaced?	☑	☐	☐
11. System meets manufacturer installation instructions?	☑	☐	☐
12. System conduit and piping securely mounted?	☑	☐	☐
13. Does system meet UL 300 standard?	☑	☐	☐
14. Employees trained in the proper operation of the system?	☑	☐	☐
15. Audible and/or visual alarms functional?	☑	☐	☐
16. System reset and placed back in service?	☑	☐	☐
17. System connected to central station?	☑	☐	☐
18. Class K extinguisher present and functional?	☑	☐	☐
19. Do hood and duct comply with NFPA #96?	☑	☐	☐
20. Company State of Ohio Certification # 53-28-1034	☑	☐	☐
21. State of Ohio Certification Jon LeRoy 54-18-1535	☑	☐	☐
22. State of Ohio Certification Randolph N Kaser 54-18-0381	☐	☐	☑
23. Complete Hydrostatic Pressure Test Current	☑	☐	☐
24. Complete 6 Year Maintenance Current	☐	☐	☑

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Fire Loss Control, Inc.
590 Pearl Road
Brunswick, Ohio 44212

Fire Suppression Systems
Service History
Order # 11586

JOB LOCATION
Suburban Pavilion
20265 Emery Road
North Randall Ohio 44128
216-475-8880
P2:
F:

CLIENT
Fire Loss Control, Inc.
590 Pearl Road
Brunswick Ohio 44212

INSPECTION

I. Fire Suppression Systems OK FAIL NA

I state that the information on this form is correct at the time and place of my inspection. And that all equipment tested at this time was left in operational condition upon completion of this inspection except as noted above.

Acquire Fire Protection, Inc. / Fire Loss Control, Inc.

Technician

X 

Jonathan LeRoy 11/4/2015

Fire Inspector

X _____

Customer Signature

X _____

*** End Report: 2 ***

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS