

Acquire Fire Protection, Inc.

17012 Kinsman Road
Middlefield, Ohio 44062

Fire Extinguishers**Service History**

Order # 11718

JOB LOCATION

Parker Hannifin
520 Ternes Avenue
Elyria Ohio 44035
440-366-1280
Service Date: 12/16/2015

P1: (440)366-1280
P2:
F:

CLIENT

Parker Hannifin
520 Ternes Avenue
Elyria Ohio 44035

CONTACT

Paul Novak

TECHNICIAN

JAL

Num S/N	Location	Size / Type	Mfg Date	Hydro Test	6 Year	Bar Code	Timestamp
1 A27572609	HR office	5 ABC	2014			AQ0001914	12/16/2015 9:07:15 AM
2 ZP282183	conference room	5 ABC	2008		2014	AQ0001922	12/16/2015 9:08:00 AM
3 ZS451453	1:N pump room	10 ABC	2008		2014	AQ0001921	12/16/2015 9:08:22 AM
4 YS294249	K4K	5 ABC	2007		2013	AQ0001923	12/16/2015 9:09:06 AM
5 YS294759	Restrooms at H4	5 ABC	2007		2013	AQ0001924	12/16/2015 9:09:31 AM
6 AE461730	Inspection storage	5 ABC	2010			AQ0001925	12/16/2015 9:10:50 AM
7 AF24293	Inspection	5 ABC	2010			AQ0001926	12/16/2015 9:10:23 AM
8 AE461735	G4	5 ABC	2010			AQ0001952	12/16/2015 9:10:01 AM
9 BW725376	E4 vending	10 ABC	2013			AQ0001927	12/16/2015 9:11:45 AM
10 YY163061	F3	5 ABC	2007		2013	AQ0001937	12/16/2015 9:11:28 AM
11 ZP284880	Outside elevator room	5 ABC	2008		2013	AQ0001911	12/16/2015 9:12:05 AM
12 YR290091	Elevator room	10 ABC	2007		2013	YR290091	12/16/2015 9:37:17 AM
13 ZP284878	Prototype Isle	5 ABC	2008		2014	AQ0001956	12/16/2015 9:12:30 AM
14 JL-572136	2:Upstairs mez cage	10 ABC	1990	2004	2010	AQ0007654	12/16/2015 9:13:40 AM
15 AF397108	2:Top Of Stais Mez	10 ABC	2011			AQ0001928	12/16/2015 9:12:58 AM
16 JG-508192	South Griding Wall	10 ABC	1990	2015		AQ0006535	12/16/2015 9:14:18 AM
17	R&D Lab 3625	2.5 ABC	1985	2012		AQ0007655	12/16/2015 9:14:54 AM
18 Y605644	electronics lab	5 CO2	2003	2014		AQ0008659	12/16/2015 9:15:18 AM
19 XL581269	R & D Hallway	10 ABC	2005		2011	AQ0001929	12/16/2015 9:16:48 AM
20 XL592938	R & D Hallway	10 ABC	2005		6/2011	AQ0001930	12/16/2015 9:17:30 AM
21 A-507970	R & D Room 100	10 ABC	2009		2015	AQ0007659	12/16/2015 9:17:52 AM
22 A-507920	R & D Room 200	10 ABC	2009		2015	AQ0007660	12/16/2015 9:18:11 AM
23 ZF-338072	R & D Room 300	10 ABC	2009		2015	AQ0007658	12/16/2015 9:18:29 AM
24 A-507720	R & D Room 400	10 ABC	2009		2015	AQ0007661	12/16/2015 9:16:30 AM
25 ZN88836	R & D Machining	10 ABC	2008	2015		AQ0009043	12/16/2015 9:16:02 AM
26 YS294748	R & D Test Cell Room	5 ABC	2007		2013	AQ0007929	12/16/2015 9:18:52 AM
27 AF396615	R & D Pump House	10 ABC	2010			AQ0001931	12/16/2015 9:19:24 AM
28 F958540	R & D Room 600	10 ABC	2009		2015	AQ0001932	12/16/2015 9:19:47 AM

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Acquire Fire Protection, Inc.

17012 Kinsman Road
Middlefield, Ohio 44062

Fire Extinguishers**Service History**

Order # 11718

JOB LOCATION

Parker Hannifin
520 Ternes Avenue
Elyria Ohio 44035
440-366-1280

P1: (440)366-1280

P2:

F:

CLIENT

Parker Hannifin
520 Ternes Avenue
Elyria Ohio 44035

Num S/N	Location	Size / Type	Mfg Date	Hydro Test	6 Year	Bar Code	Timestamp
29 BV623930	R & D Storage Room	5 ABC	2013			AQ0001933	12/16/2015 9:20:14 AM
30 SW908215	R & D Office	10 ABC	2002	2015		AQ0009044	12/16/2015 9:20:33 AM
31 AE461733	R & D	5 ABC	2010			AQ0001934	12/16/2015 9:21:05 AM
32 CG594799	SO. Employee Rest rm	10 ABC	2014			AQ0001939	12/16/2015 9:21:44 AM
33 JY-5060007	EH Assembly	10 ABC	1991	2015		AQ0008355	12/16/2015 9:22:31 AM
34 LV-082244	EH Pump House	10 ABC	1993	2006	2012	LV-082244	12/16/2015 9:23:11 AM
35 F957161	Republic Paint Booth	10 ABC	2009		2015	AQ0001935	12/16/2015 9:24:15 AM
36 AF394641	republic assembly	10 ABC	2011			AQ0001936	12/16/2015 9:23:51 AM
37 ZL381927	Shipping LD	10 ABC	2008		2014	AQ0001957	12/16/2015 9:24:58 AM
38 AP942316	D2	10 ABC	2011			AP942316	12/16/2015 9:25:39 AM
39 AF24387	F2	5 ABC	2010			AQ0001938	12/16/2015 9:26:10 AM
40 AP955578	E1	10 ABC	2011			AQ0001940	12/16/2015 9:26:42 AM
41 LV-080676	G1	10 ABC	1993	2005	2011	AQ0001942	12/16/2015 9:27:13 AM
42 YL76682	E1	10 ABC	2007		2013	AQ0001941	12/16/2015 9:27:36 AM
43 AF05771	Spare	5 ABC	2010		2013	AF05771	12/16/2015 9:28:21 AM
44 JL-563361	Spare	10 ABC	1990	2004	2013	AQ0007650	12/16/2015 9:28:08 AM
45 LV-080679	Spare	10 ABC	1993	2005	2013	LV-080679	12/16/2015 9:28:59 AM
46 BC158223	Spare	10 ABC	2012			BC158223	12/16/2015 9:28:39 AM
47 YR284699	Main Hydraulic Pump House	10 ABC	2007		2013	AQ0001954	12/16/2015 9:29:42 AM
48 ZA816279	Hydraulic Pump House Welding Table	10 ABC	2007		2013	AQ0001953	12/16/2015 9:29:58 AM
49 AF07768	Maintenance	5 ABC	2010			AQ0001955	12/16/2015 9:30:17 AM
50 YW259163	Laser room	5 ABC	2007		2013	AQ0007930	12/16/2015 9:30:57 AM
51 LV-080614	H1	10 ABC	1993	2006	2012	AQ0001943	12/16/2015 9:31:52 AM
52 LV-080680	J2	10 ABC	1993	2005	2013	AQ0001944	12/16/2015 9:32:14 AM
53 YS296662	K1	5 ABC	2007		2013	AQ0001945	12/16/2015 9:32:43 AM
54 S-164123	K1 Air compressor	15 CO2	1978	2015		AQ0004612	12/16/2015 9:33:10 AM
55 YS294251	K3 Man door	5 ABC	2007		2013	AQ0001946	12/16/2015 9:33:37 AM
56 ZL914311	J3	5 ABC	2008		2014	AQ0001947	12/16/2015 9:34:12 AM
57 YR288303	J3	10 ABC	2007		2013	AQ0001949	12/16/2015 9:34:29 AM

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Acquire Fire Protection, Inc.

17012 Kinsman Road
Middlefield, Ohio 44062

Fire Extinguishers**Service History**

Order # 11718

JOB LOCATION

Parker Hannifin
520 Ternes Avenue
Elyria Ohio 44035
440-366-1280

P1: (440)366-1280

P2:

F:

CLIENT

Parker Hannifin
520 Ternes Avenue
Elyria Ohio 44035

Num S/N	Location	Size / Type	Mfg Date	Hydro Test	6 Year	Bar Code	Timestamp
58 AC577427	Upstairs plant office	5 ABC	2010			AQ0001950	12/16/2015 9:35:03 AM
59 YR290081	Tool Room	10 ABC	2007		2013	AQ0001948	12/16/2015 9:35:38 AM
60 BW723241	G3	10 ABC	2013			AQ0001951	12/16/2015 9:36:15 AM
61 CE517599	2:Training office hall	5 ABC	2014			AQ0001920	12/16/2015 9:38:44 AM
62 AC577424	2:Lunch area hall	5 ABC	2010			AQ0001919	12/16/2015 9:39:21 AM
63 A27574135	2:lunchroom	5 ABC	2014			AQ0001918	12/16/2015 9:40:07 AM
64 XV147073	office	5 ABC	2006		2012	AQ0001913	12/16/2015 9:40:58 AM
65 YS294757	office	5 ABC	2007		2013	AQ0001912	12/16/2015 9:41:38 AM
66 BJ807428	pump house	10 ABC	2012			AQ0001958	12/16/2015 9:42:41 AM
67 A27572613	office	5 ABC	2014			AQ0001917	12/16/2015 9:44:12 AM
68 A27574131	Office cubicles	5 ABC	2014			AQ0001916	12/16/2015 9:44:51 AM
69 M-746549	IT Server Room 3764	5 HALON	1998	2010		AQ0007663	12/16/2015 9:45:39 AM
70 D009838	computer storage	13 HALON	1985	2010		AQ0007644	12/16/2015 9:46:02 AM
71 A27573612	:Office cubicles	5 ABC	2014			AQ0001915	12/16/2015 9:46:34 AM

Extinguisher Work Summary as of 12/16/2015

	Hydro Test	6 Year	Annual	Monthly	Recharge	New	Monthly	Other	Totals
ABC	0	0	0	67	0	0	0	0	67
CO2	0	0	0	2	0	0	0	0	2
HALON	0	0	0	2	0	0	0	0	2
Totals	0	0	0	71	0	0	0	0	71

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS