

Fire Loss Control, Inc.590 Pearl Road
Brunswick, Ohio 44212**Fire Extinguishers****Service History**

Order # 11765

JOB LOCATIONCandlewood Park Healthcare Center
1835 Belmore Road
East Cleveland Ohio 44112
216-268-3600

P1: (216)268-3600

P2:

F:

Service Date: 12/17/2015

CLIENTFire Loss Control, Inc.
590 Pearl Road
Brunswick Ohio 44212**CONTACT**

Frank Diasecki

TECHNICIAN

JAL

Num S/N	Location	Size / Type	Mfg Date	Hydro Test	6 Year	Bar Code	Timestamp
1 ZX564741	3:Behavior unit	10 ABC	2009		2015	ZX564741	12/17/2015 11:01:03 AM
2 TB-602042	3:Nurses station	10 ABC	2002	2014		TB-602042	12/17/2015 10:03:29 AM
3 N160472	3:Nurses station	10 ABC	2010			N160472	12/17/2015 10:07:58 AM
4 N160493	3:Hall at rm 330	10 ABC	2010			N160493	12/17/2015 10:10:37 AM
5 N159492	3:Hall at rm 333	10 ABC	2009		2015	N159492	12/17/2015 10:13:06 AM
6 Z926718	2:Hall at 226	10 ABC	2010		2014	Z926718	12/17/2015 10:17:01 AM
7 N160513	2:Hall at rm 223	10 ABC	2010			N160513	12/17/2015 10:19:20 AM
8 N159586	2:Nurses station	10 ABC	2009		2015	N159586	12/17/2015 10:21:16 AM
9 N160474	2:Hall at rm 211	10 ABC	2010			N160474	12/17/2015 10:23:54 AM
10 A32927196	2:Hall at rm 208	10 ABC	2015			AQ10097	12/17/2015 10:28:18 AM
11 YK557126	1:Hall at rm 119	5 ABC	2007		2011	YK557126	12/17/2015 10:30:59 AM
12 N160486	1:Hall at rm 123	10 ABC	2010			N160486	12/17/2015 10:32:54 AM
13 N160476	1:Admin office	10 ABC	2010			N160476	12/17/2015 10:41:47 AM
14 VY-107690	1:Nurses station	5 ABC	2003	2015		VY-107690	12/17/2015 10:35:34 AM
15 A32842878	1:PT rm	5 ABC	2015			AQ10098	12/17/2015 10:38:47 AM
16 N160202	1:Hall at rm 101	10 ABC	2009		2015	N160202	12/17/2015 10:44:55 AM
17 HU-331333	1:Hall at rm 104	10 ABC	1988	2012		AQ10099	12/17/2015 10:48:32 AM
18 N160494	LL:Laundry	10 ABC	2010			N160494	12/17/2015 10:51:33 AM
19 YE611378	LL:Hall at boiler rm	10 ABC	2006		2012	YE611378	12/17/2015 10:53:45 AM
20 N160487	LL:Boiler rm	10 ABC	2010			N160487	12/17/2015 10:57:16 AM
21 XL565603	LL:Maintenance	10 ABC	2005		2012	XL565603	12/17/2015 10:59:01 AM
22 YP-647956	LL:Maint. spare	5 ABC	2007		2013	YP-647956	12/17/2015 11:26:56 AM
23 N160501	LL:Elevator rm	10 ABC	2010			N160501	12/17/2015 11:09:59 AM
24 SF-651049	LL:Hall by time clock	10 ABC	2001	2015		SF-651049	12/17/2015 11:04:26 AM
25 ZU145787	LL:Hall at restrooms	10 ABC	2008		2014	ZU145787	12/17/2015 11:08:03 AM
26 AA-383435	LL:Kitchen	6 Liter Class K	2003	2015		AA-383435	12/17/2015 11:12:42 AM
27 AD-634132	LL:Kitchen	6 Liter Class K	2013			AD-634132	12/17/2015 11:15:39 AM
28 ZU145771	LL:Hall at dish counter	10 ABC	2008		2014	ZU145771	12/17/2015 11:17:49 AM

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Fire Loss Control, Inc.

590 Pearl Road
 Brunswick, Ohio 44212

Fire Extinguishers**Service History**

Order # 11765

JOB LOCATION

Candlewood Park Healthcare Center
 1835 Belmore Road
 East Cleveland Ohio 44112
 216-268-3600

P1: (216)268-3600

P2:

F:

CLIENT

Fire Loss Control, Inc.
 590 Pearl Road
 Brunswick Ohio 44212

Extinguisher Work Summary as of 12/17/2015

	Hydro Test	6 Year	Annual	Monthly	Recharge	New	Monthly	Other	Totals
ABC	0	0	26	0	0	0	0	0	26
Class K	0	0	2	0	0	0	0	0	2
Totals	0	0	28	0	0	0	0	0	28

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS