

**Acquire Fire Protection, Inc.**17012 Kinsman Road  
Middlefield, Ohio 44212**Fire Suppression Systems****Service History**

Order # 11806

**JOB LOCATION**Zeppes Pizza/Perry  
2739 North Ridge Road Suite 1  
(440)392-9490  
Painesville OH 44077  
Service Date: 2/4/2016P1: (440)392-9490  
P2:  
F:**CLIENT**Zeppes Pizza  
2739 North Ridge Road Suite 1  
Painesville OH 44077**CONTACT**

Greg

(440)392-9490

**TECHNICIAN**

JAL

**Fire Suppression System**

Num: 1

Type: Wet Chemical Extinguishing System

Manufacturer: Amerex

Model: KP 3.75

Location: Kitchen

Install Date: 2000

Last Service: 2/2016

Duct Size: 14" X 14"

Nozzle Type: 16416

Plenum Size: 18" X 10Ft

Nozzle Type: 11982

Serial #: TBU033464

Bar Code: AQ0006027

Timestamp:

**Tests/Inspections/Services**

Description	Last	Due
Hydro Test	2012	<input type="checkbox"/>
Monthly		<input type="checkbox"/>
Recharge	8/2/2012	<input type="checkbox"/>
Semi-Annual	2/2016	<input checked="" type="checkbox"/>
Flush Piping		<input type="checkbox"/>
New		<input type="checkbox"/>

**Cylinders**

Num	Size	Type	Mfg Date	Hydro	6 Year	S/N	Bar Code	Timestamp
1	3.75	Extinguishing Agent	6/2000	8/2/2012		72765 AX		

**Replacement Parts**

Qty	Description	Part No.	Replaced
1	Fuse Links 360°F K Link	360K-11	2/4/2016
6	Amerex Nozzle Cap	12334	7/2015
2	Fuse Links 450°F K Link	450K-11	2/4/2016

**Appliances (Left to Right)**

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Printed on: 2/11/2016 12:02:37 PM

**Acquire Fire Protection, Inc.**17012 Kinsman Road  
Middlefield, Ohio 44212**Fire Suppression Systems****Service History**

Order # 11806

**JOB LOCATION**Zepe's Pizza/Perry  
2739 North Ridge Road Suite 1  
(440)392-9490  
Painesville OH 44077P1: (440)392-9490  
P2:  
F:**CLIENT**Zepe's Pizza  
2739 North Ridge Road Suite 1  
Painesville OH 44077

Num	Description	Size	Nozzle(s)
1	Range - 4 Burner		14178
2	Fryer - Gas		13729
3	Fryer - Gas		13729

**INSPECTION****I. Fire Suppression Systems**

	Yes	No	NA
1. Hood and appliances properly protected?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Was nozzle/appliance alignment correct upon arrival?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
If not was the alignment corrected during inspection?			
3. System cylinder gauge in operable range?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Cylinder weight or liquid level OK?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Fusible links replaced?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Actuation cartridge weight or gauge in operable range?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
/* Pressure Gage reading 2000 PSI */			
7. Complete fuel shut-down operational?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Remote pull station accessible and operational?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. All components clean and free of grease?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Nozzle caps cleaned or replaced?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. System meets manufacturer installation instructions?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. System conduit and piping securely mounted?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Does system meet UL 300 standard?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Employees trained in the proper operation of the system?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Audible and/or visual alarms functional?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. System reset and placed back in service?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. System connected to central station?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
18. Class K extinguisher present and functional?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. Do hood and duct comply with NFPA #96?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Company State of Ohio Certification # 53-28-1034	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. State of Ohio Certification Jon LeRoy 54-18-1535	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. State of Ohio Certification Randolph N Kaser 54-18-0381	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
23. Complete Hydrostatic Pressure Test Current	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
24. Complete 6 Year Maintenance Current	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

I state that the information on this form is correct at the time and place of my inspection. And that all equipment tested at this time was left in operational condition upon completion of this inspection except as noted above.

Acquire Fire Protection, Inc. / Fire Loss Control, Inc.

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Printed on: 2/11/2016 12:02:37 PM

**Acquire Fire Protection, Inc.**

17012 Kinsman Road  
Middlefield, Ohio 44212

**Fire Suppression Systems**

**Service History**

Order # 11806

**JOB LOCATION**

Zeppe's Pizza/Perry  
2739 North Ridge Road Suite 1  
(440)392-9490  
Painesville OH 44077

P1: (440)392-9490  
P2:  
F:

**CLIENT**

Zeppe's Pizza  
2739 North Ridge Road Suite 1  
Painesville OH 44077

**Technician**

X 


Jon LeRoy

2/4/2016

**Customer Signature**

X \_\_\_\_\_

**Fire Inspector**

X 

Greg

2/4/2016

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Printed on: 2/11/2016 12:02:37 PM