

Acquire Fire Protection, Inc.17012 Kinsman Road
Middlefield, Ohio 44062**Fire Suppression Systems****Service History**

Order # 12135

JOB LOCATIONOlde Towne Grille
15924 W High Street
440-632-0932
Middlefield OH 44062
Service Date: 3/22/2016P1: (440)632-0932
P2:
F:**CLIENT**Olde Towne Grille
15924 W High Street
Middlefield Ohio 44062**CONTACT**

AI

TECHNICIAN

MRO

Fire Suppression SystemNum: 1
Type: Wet Chemical Extinguishing System
Manufacturer: Amerex
Model: KP 4.75
Location: Kitchen
Install Date: 8/2014
Last Service: 9/29/2015Serial #: A8867
Bar Code: AQ0008803
Timestamp: 3/22/2016 4:19:07 PM**Tests/Inspections/Services**

Description	Last	Due
Hydro Test	2014	<input type="checkbox"/>
Monthly		<input type="checkbox"/>
Recharge		<input type="checkbox"/>
Semi-Annual	3/2016	<input checked="" type="checkbox"/>
Flush Piping		<input type="checkbox"/>
New	8/5/2014	<input type="checkbox"/>

Cylinders

Num	Size	Type	Mfg Date	Hydro	6 Year	S/N	Bar Code	Timestamp
1	4.75	Extinguishing Agent	2014	2014		A8867		

Replacement Parts

Qty	Description	Part No.	Replaced
5	Fuse Links 450°F K Link	450K-11	9/29/2015
2	Fuse Links 360°F K Link	360K-11	3/3/2015
11	Amerex Nozzle Cap	12334	8/2014

INSPECTION**I. Fire Suppression Systems**

Yes No NA

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Acquire Fire Protection, Inc.

17012 Kinsman Road
Middlefield, Ohio 44062

Fire Suppression Systems

Service History

Order # 12135

JOB LOCATION

Olde Towne Grille
15924 W High Street
440-632-0932
Middlefield OH 44062

P1: (440)632-0932
P2:
F:

CLIENT

Olde Towne Grille
15924 W High Street
Middlefield Ohio 44062


INSPECTION

- 1. Hood and appliances properly protected?
- 2. Was nozzle/appliance alignment correct upon arrival?
- If not was the alignment corrected during inspection?
- 3. System cylinder gauge in operable range?
- 4. Cylinder weight or liquid level OK?
- 5. Fusible links replaced?
- 6. Actuation cartridge weight or gauge in operable range?
- 7. Complete fuel shut-down operational?
- 8. Remote pull station accessible and operational?
- 9. All components clean and free of grease?
- 10. Nozzle caps cleaned or replaced?
- 11. System meets manufacturer installation instructions?
- 12. System conduit and piping securely mounted?
- 13. Does system meet UL 300 standard?
- 14. Employees trained in the proper operation of the system?
- 15. Audible and/or visual alarms functional?
- 16. System reset and placed back in service?
- 17. System connected to central station?
- 18. Class K extinguisher present and functional?
- 19. Do hood and duct comply with NFPA #96?
- 20. Company State of Ohio Certification # 53-28-1034
- 21. State of Ohio Certification Jon LeRoy 54-18-1535
- 22. State of Ohio Certification Marcus R Orahood 54-78-1475
- 23. Complete Hydrostatic Pressure Test Current
- 24. Complete 6 Year Maintenance Current

I state that the information on this form is correct at the time and place of my inspection. And that all equipment tested at this time was left in operational condition upon completion of this inspection except as noted above.

Acquire Fire Protection, Inc. / Fire Loss Control, Inc.

Technician

X 

Marcus R Orahood

3/22/2016

Customer Signature

X 

AI

3/22/2016

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Acquire Fire Protection, Inc.

17012 Kinsman Road
Middlefield, Ohio 44062

Fire Suppression Systems

Service History

Order # 12135

JOB LOCATION

Olde Towne Grille
15924 W High Street
440-632-0932
Middlefield OH 44062

P1: (440)632-0932
P2:
F:

CLIENT

Olde Towne Grille
15924 W High Street
Middlefield Ohio 44062

Fire Inspector

X

*** End Report: 1 ***

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS

Printed on: 3/28/2016 12:53:30 PM