

Fire Loss Control, Inc.590 Pearl Road
Brunswick, Ohio 44212**Fire Extinguishers****Service History**

Order # 12141

JOB LOCATIONMueller Art Cover & Binding Co
12005 Alameda Drive
Strongsville Ohio 44149
440-238-3303

P1: (440)238-3303

P2:

F:

CLIENTFire Loss Control Inc.
590 Pearl Road
Brunswick Ohio 44212

Service Date: 4/21/2016

CONTACT

Bob Mueller

TECHNICIAN

MRO

Num S/N	Location	Size / Type	Mfg Date	Hydro Test	6 Year	Bar Code	Timestamp
1 GJ-407647	4849 ODH	10 ABC	1986	2011		AQ0008180	4/21/2016 11:49:12 AM
2 RK-730129	4844 Shipping desk	10 ABC	2000	2012		AQ0008181	4/21/2016 11:45:22 AM
3 MV-896999	6214 lunch rm	10 ABC	1997	2014		MV-896999	
4 AJ479349	4839 print rm	5 ABC	2011			AJ479349	
5 RK-464230	4841 office	5 ABC	2000	2012		AQ0008188	4/21/2016 11:32:36 AM
6 N-313423	4845 assembly	10 ABC	2010		2016*	N-313423	4/21/2016 11:48:37 AM
7 PS-99649	4840 crathorn rm	10 ABC	1998	2011		AQ0008182	4/21/2016 11:35:58 AM
8 KL-00609965	6213 Silk screen exit	10 ABC	1992	2011		AQ0008183	4/21/2016 11:37:44 AM
9 N-313433	4847 Exit door	10 ABC	2010		2016*	N-313433	4/21/2016 11:38:52 AM
10 N-313439	4848 vinyl	10 ABC	2010		2016*	N-313439	4/21/2016 11:43:06 AM
11 RR-556538	4838 maintenance	10 ABC	2000	2012		AQ0008184	4/21/2016 11:43:50 AM
12 PS-98498	4842 garage	10 ABC	1998	2011		AQ0008185	4/21/2016 11:51:25 AM
13 GJ-407671	7493 Garage	10 ABC	1986	2013		AQ0008187	
14 RP-667576	4846 Rear dock	10 ABC	2000	2012		AQ0008186	4/21/2016 11:41:11 AM
15 AK488487	4797 Rear w/h	5 ABC	2011			AK488487	
16 AK487892	4798 Rear w/h	5 ABC	2011			AK487892	
17 AK488620	4800 Rear WH	5 ABC	2011			AK488620	
18 AK464865	4799 Rear WH	5 ABC	2011			AK464865	
19	7494 spare	10 ABC	1998	2013			*** Missing ***

Extinguisher Work Summary as of 4/21/2016

	Hydro Test	6 Year	Annual	Monthly	Recharge	New	Monthly	Other	Totals
ABC	0	3	15	0	0	0	0	1	19
Totals	0	3	15	0	0	0	0	1	19

ALL WORK DONE IN ACCORDANCE WITH N.F.P.A. STANDARDS